

Underground Workings
Vredehoek Tin Mine
surveyed by A. Kdiasnikoff
S. Baumann
23/10/94
main shaft
flooded shaft
4m
21,4m
water
Entrance